

1007

NOTE:

Final plot, solid line, shows coverage obtained by Camera No. 1
(coverage is from horizon to horizon).

REMARKS:

Camera No. 1:

1. Clock recording not readable.
2. Film advance malfunction resulting in varying size frames.
3. Quality of positive -- good.

Cameras No. 2 and 4:

1. Vignetting -- corners very thin.
2. Clock and counters not readable on prints (generally good on negative).
3. Quality -- good.
4. Scratches in line of flight (frame 228 forward).
5. Print for camera not printed in reverse.
6. Fiducial marks reversed.

Camera No. 3:

1. Shutter malfunction -- only every 5th frame useable.
2. Frame counter malfunction.
3. Clock and counter not readable.
4. Fiducial marks reversed.
5. Quality -- good.
6. Scratches.

Camera No. 5:

1. Counter malfunction -- 684, 697, 736.
2. Static marks.
3. Scratches -- 728 (start of scratch), 740 (start of scratch), and 737(emulsion).
4. Counter and clock not readable on prints.
5. Prints, in some cases, did not reproduce detail present on negative -- 742 and 771.
6. Contrast -- in some cases poor (not always due to haze).